Please print or type in the unshaded areas only (fill-in areas are spaced for elite type, i.e. 12 character/inch).

DOE/RL-88-21 216-U-12 Crib Rev. 3, 6/30/94

A. PROCESS

FORM 3	DANGEROUS WASTE PERMIT APPLICATION I. EPA/STATE I.D. NUMBER W A 7 8 9 0 0 0 8 9 6 7								
FOR OFFICIAL USE ONLY									
APPLICATION APPROVED DATE RECEIVED (mo., day, & yr.) COMMENTS									
		_		Pending Approval					
II. FIRST OR REVISED APPLICATION									
application. If			below (mark one box only) to indicate whe you already know your facility's EPA/STA						
MO. DAY YEAR D. THE STATE OF TH			and provide the appropriate date) the instructions for definition of "existing" facility. Tomplete Item below.) OR EXISTING FACILITIES, PROVIDE THE ATE (mo., day, & yr.) OPERATION BEGAN OR the DATE CONSTRUCTION COMMENCED (use to boxes to the left) The date construction of the Hanford Facility the memorial of the manner of the service of the left of the date construction of the Hanford Facility the memorial of the service of the left						
B. REVISED 1. F	B. REVISED APPLICATION (place an "X" below and complete Section I above) 1. FACILITY HAS AN INTERIM STATUS PERMIT 2. FACILITY HAS A FINAL PERMIT								
III. PROCES	S - CODES AND CAP	ACITIES							
codes. If process (B. PROCES 1. AMOU 2. UNIT Only to Storage:	more lines are needed fincluding its design ca SS DESIGN CAPACIT JNT - Enter the amour OF MEASURE - For e	d, enter the pacity) in Y - For each nt. each amou	the list of process codes below that best of a code(s) in the space provided. If a procest the space provided on the (Section III-C). In characteristic code entered in column A enter the capable of the space provided on the (Section III-C). In the code entered in column B(1), enter the code end below should be used. APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY GALLONS OR LITERS	ess will be used that is not in pacity of the process.	ncluded in the list	at describes the unit of measure used. O- APPROPRIATE UNITS OF SS MEASURE FOR PROCESS DE DESIGN CAPACITY			
TANK WASTE PI	ILE IMPOUNDMENT N WELL	S02 S03 S04	GALLONS OR LITERS CUBIC YARDS OR CUBIC METERS GALLONS OR LITERS GALLONS OR LITERS ACRE-FEET (the volume	SURFACE IMPOUNDMENT SURFACE IMPOUNDMENT TO2 GALLONS PER DAY OR LITERS PER DAY LITERS PER DAY TONS PER HOUR OR METRIC TONS PER HOUR; GALLONS PER HOUR OR LITERS PER HOUR OR LITERS PER HOUR					
LAND APF OCEAN DI	PLICATION	D82 D83	that would cover one acre to a depth of one foot) OR HECTARE-METER ACRES OR HECTARES GALLONS PER DAY accurring in tanks, surface impoundments or incinerators. LITERS PER DAY Describe the processes in the						
UNIT OF N	MEA	T OF SURE DDE	UNIT OF MEASURE	UNIT OF MEASURE CODE	UNIT OF MEAS	UNIT OF MEASURE SURE CODE			
LITERS CUBIC YA CUBIC ME	GALLONS G LITERS PER DAY V ACRE-FEET A LITERS L TONS PER HOUR D HECTARE-METER F CUBIC YARDS Y METRIC TONS PER HOUR W ACRES B CUBIC METERS C GALLONS PER HOUR E HECTARES Q GALLONS PER DAY U LITERS PER HOUR H				TER F B Q				
	EXAMPLE FOR COMPLETING SECTION III (shown in line numbers X-1 and X-2 below): A facility has two storage tanks; one tank can hold 200 gallons and the other can hold 400 gallons. The facility also has an incinerator that can burn up to 20 gallons per hour.								

B. PROCESS DESIGN CAPACITY

216-U-12 Crib, Rev. 3 Page 2 of 9

LINE NUMBER	CODE (from list above)	1. AMOUNT (specify)	2. UNIT OF MEASURE (enter code)	FOR OFFICIAL USE ONLY			
X-1	S02	600	G				
X-2	T03	20	Е				
1	D81	50,000	U				
2							
3							
4							
5							
6							
7							
8							
9							
10							

C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESS (CODE "T04"). FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY.

D81

The 216-U-12 Crib was used to dispose of UO₃ (uranium-oxide) Plant corrosive process condensate. The 216-U-12 Crib, a percolation unit, was designed to receive mixed waste from the UO₃ Plant for approximately 5 minutes every hour, 100 gallons (379 liters) per minute, and to dispose of the process condensate by percolation into the soil column.

Process condensate discharges were considered only a dangerous waste due to corrosivity caused by UO₃ Plant operations. After January 1987, process condensate was administratively controlled to prevent corrosive dangerous waste discharge to the 216-U-12 Crib. The unit continued to receive process condensate until the crib pipelene was cut and permanently capped on January 30, 1988. The 216-U-12 Crib will be closed under interim

216-U-12 Crib, Rev. 3 Page 3 of 9

IV. DESCRIPTION OF DANGEROUS WASTES

A. DANGEROUS WASTE NUMBER - Enter the four digit number from Chapter 173-303 WAC for each listed dangerous waste you will handle. If you handle dangerous wastes which are not listed in Chapter 173-303 WAC, enter the four digit number(s) that describe the characteristics and/or the toxic contaminants of those dangerous wastes.

- B. ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

 ENGLISH UNIT OF MEASURE CODE

 METRIC UNIT OF MEASURE CODE

POUNDS P KILOGRAMS K
TONS T METRIC TONS M

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

D. PROCESSES

1. PROCESS CODES:

For listed dangerous waste: For each listed dangerous waste entered in column A select the code(s) from the list of process codes contained in Section III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed dangerous wastes: For each characteristic or toxic contaminant entered in Column A, select the code(s) from the list of process codes contained in Section III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed dangerous wastes that possess that characteristic or toxic contaminant.

Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: DANGEROUS WASTES DESCRIBED BY MORE THAN ONE DANGEROUS WASTE NUMBER - Dangerous wastes that can be described by more than one Waste Number shall be described on the form as follows:

- 1. Select one of the Dangerous Waste Numbers and enter it in column A. On the same line complete columns B, C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
- 2. In column A of the next line enter the other Dangerous Waste Number that can be used to describe the waste. In column D(2) on that line enter "Included with above" and make no other entries on that line.
- 3. Repeat step 2 for each other Dangerous Waste Number that can be used to describe the dangerous waste.

EXAMPLE FOR COMPLETING SECTION IV (shown in line numbers X-1, X-2, X-3, and X-4 below) - A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

L	A. DANGEROUS		C. UNIT	D. PROCESSES					
I N NO E .	WASTE NO. (enter code)	/ASTE NO. QUANTITY OF WASTE SURE (enter		1. PROCESS CODES (enter)				PROCESS DESCRIPTION (if a code is not entered in D(1))	
X-1	K054	900	P	T03	D80				
X-2	D002	400	P	T03	D80				
X-3	D001	100	P	T03	D80				
X-4	D002			T03	D80			included with above	
1	D002	4,454,000	Р	D81				Percolation	
2									
3									
4									
5									
6									
7									
8									
9									
10									

E. USE THIS SPACE TO LIST ADDITIONAL PROCESS CODES FROM SECTION D(1) ON PAGE 3.

216-U-12 Crib, Rev. 3 Page 4 of 9

were implemented to neutralize the condensate before discharge. Waste consisted of process condensate off-gases from the production of UO₃ powder from uranium nitrate hexahydrate solutions. When the plant was operating, the pH of this waste ranged from 0.5 to 1.5.

When the $\mathrm{UO_3}$ Plant was shut down for periods of time, the pH of the process condensate ranged from 2.0 to 4.0. The $\mathrm{UO_3}$ plant has been permanently shut down and no process condensate is being discharged to the 216-U-12 Crib. Past process rates show that approximately 1,700,000 gallons (6,440,000 liters) per year of process condensate were disposed in the 216-U-12 Crib.

V. FACILITY DRAWING Refer to attached drawing(s).

All existing facilities must include in the space provided on page 5 a scale drawing of the facility (see instructions for more detail).

VI. PHOTOGRAPHS Refer to attached photograph(s).

All existing facilities must include photographs (arial or ground-level) that clearly delineate all existing structures; existing storage, treatment and disposal areas; and sites of future storage, treatment or disposal areas (see instructions for more detail).

VII. FACILITY GEOGRAPHIC LOCATION This information is provided on the attached drawing(s) and photograph(s).

	3() 1 3 1 ()			
LATITUDE (degrees, minutes, & seconds)	LONGITUDE (degrees, minutes, & seconds)			

216-U-12 Crib, Rev. 3 Page 5 of 9

VIII. FACILITY OWNER						
A. If the facility owner is also the facility operator as listed below. B. If the facility owner is not the facility operator as listed	d in Section VII on Form 1, "General Information", place an " in Section VII on Form 1, complete the following items:	X" in the bo	ox to the left and skip to Section IX			
1. NAME OF FACILITY'S LEGAL OWNER 2. PHONE NO. (area code						
3. STREET OR P.O. BOX	4. CITY OR TOWN	5. ST.	6. ZIP CODE			
IX. OWNER CERTIFICATION						
I certify under penalty of law that I have personally examined a inquiry of those individuals immediately responsible for obtaining there are significant penalties for submitting false information,	ng the information, I believe that the submitted information is					
NAME (print or type)	SIGNATURE	DATE SIGNED				
John D. Wagoner, Manager U.S. Department of Energy Richland Operations Office	John D. Wagoner	06/30/1994				
X. OPERATOR CERTIFICATION						
I certify under penalty of law that I have personally examined a inquiry of those individuals immediately responsible for obtaining there are significant penalties for submitting false information,	ng the information, I believe that the submitted information is					
NAME (print or type)	SIGNATURE	DATE SIG	NED			
SEE ATTACHMENT						


216-U-12 Crib, Rev. 3 Page 6 of 9

X. OPERATOR CERTIFICATION


I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

John D. Wagoner	6/30/94
Owner/Operator	Date
John D. Wagoner, Manager	
U.S. Department of Energy	
Richland Operations Office	
Edward S. Keen	6/30/94
Co-Operator	Date
Edward S. Keen, President	
Bechtel Hanford, Inc.	

216-U-12 Crib Site Plan



39405155.6



2B8707-13.80

216-U-12 Crib, Rev. 3 Page 9 of 9

216-U-12 CRIB



46°32'27" 119°37'15"

8704509-1CN (PHOTO TAKEN 1987)